

North America Emission Control Area Fuel Oil Non-Availability Report

ECA0100

1

2

##

##(Include Double Pound for comments, not form fields)

##Report Form ID

Ship Operator Name

Pacific Basin Chartering Ltd

3

4

5

6

7

Vessel Name	Flag Country	IMO ID Number	Date of ECA First Notice	Location of ECA First Notice
Moon River	HONGKONG	9228227	1-Aug-13	Changshu, China

Name of Ports after First Notice	Name of Last Port before ECA Entry
Chongming, China	Chongming, China

Name of Port with Fuel Oil Supply Disruption	Name of Original Fuel Supplier with Disruption
N/A	N/A

12

13

14

Number of Fuel Suppliers Contacted	Date of Entry in the ECA	Time of Entry in the ECA
N/A	22-Aug-13	0200LT

15

16

17

Sulfur Content of Non-Compliant Fuel Oil	Projected Hours on Main Propulsion	Name of First POC
2.7		175 Prince Rupert, Canada

Compliance Fuel Oil Available at First POC? Plan to Bunker Compliant Fuel Oil at First POC?
No No

20

21

22

Number of fuel suppliers contacted at First POC	Name of Second POC	Compliant Fuel Oil at Second POC?
3	N/A	N/A

Plan to Bunker Compliance Fuel Oil at Second POC?	Number of Fuel Suppliers Contacted at the Second POC?
N/A	N/A

25

26

27

Date of Exit from ECA?	Time of Exit from ECA?	Has this vessel operated in the ECA in previous 12 months?
2-Sep-13	12:00LT	NO

28

29

30

Number of Separate Visits to the ECA	Number of Ports visited in the ECA	Previously submitted ECA0100 forms?
1	1	NO

31

32

33

Number of Submitted Reports	Designated Corporate Official Name	Designated Corporate Official E-mail
NO	Pacific Basin Chartering Limited	bunkers@pacificbasin.com

Designated Corporate Official Phone Number
852 2233 7222

Description of Actions to Achieve Compliance

Suppliers in Shanghai and Prince Rupert were contacted regarding LSIFO availability however, no supplier were available at t